


Admin Building 1st Floor



Building Modifications

- Remove furniture in lower left conference room and add larger conference table and chairs.
- Improve reception area to improve customer experience -- no receptionist, self-serve system

Admin Building 2nd Floor

