

4/15/20

Re: A.F. Wendling Foods Equipment

Walk-in Freezer Equipment:

Center Freezer:

Unit #1: New condensing unit and evaporator coil were installed in September 2017; unit had a 1-year parts and 5-year compressor warranty.

Unit #2: New condensing unit was installed in December 2010 and connected to the original evaporator coil. The Thermobank was replaced in December 2016.

Unit #3: New condensing unit was installed in December 2001 and connected to the original evaporator coil. The compressor was replaced in October 2007.

West Freezer:

Unit #4: Installed new in October 2003 and the compressor was last replaced in July 2010. The unit was shut down in January 2019 by customer.

Unit #5: Installed new in October 2003 and the compressor was last replaced in August 2018. The unit was shut down in January 2019 by customer.

Unit #6: Installed new in October 2003 and the compressor was last replaced in November 2003. The unit was shut down in January 2019 by customer.

Walk-in Cooler Equipment:

Produce cooler: In December 2001 we installed the unit from the old cheese cooler on roof and connected to the original evaporator.

Walk-in Meat & Cheese Cooler: Cooler enlarged in May 2004 and we installed 4 new evaporator coils and 2 new condensing units. We relocated the original unit to cooler outside and connected to 2 of the new evaporator coils.

SERVICE NOTES:

Unit #2 to walk-in cooler has a noisy compressor.

Unit #3 compressor is a 1996 model and system runs on the R-12 replacement refrigerant of R-401A.

Units #1 & #2 run on R-22 refrigerant.

Produce cooler evaporator coil has small leaks, system has been converted to R-134A refrigerant.

Fan guards on freezer evaporator to units #2 & #3 replaced in December 2016.

Freezer units #4, #5 & #6 running on replacement refrigerant R-402A.

Freezer units #2 & #3 have original evaporators from early 1960's.

Freezer units #1, #2 & #3 run on new refrigerant R-404.